



Appliance Number	Description	Class	Inspection Frequency	Test Date	Earth	Ins	Leak	Pass/Fail	Re-Test Date	Earth	Ins	Leak	Pass/Fail
					( $\Omega$ )	( $M\Omega$ )	(mA)		Visual	( $\Omega$ )	( $M\Omega$ )	(mA)	
1	Coldroom	1	Visual 6mths & inspection test 12mths	08/03/2019	0.13	33		Pass	08/09/2019				
2	Coldroom Mains Cable	1	Visual 6mths & inspection test 12mths	08/03/2019	0.04	200		Pass	08/09/2019				
3	32A / 2(16A) Splitter	1	Visual 6mths & inspection test 12mths	08/03/2019	0.04	200		Pass	08/09/2019				
4	Orange Extension Cable	1	Visual 6mths & inspection test 12mths	08/03/2019	0.05	200		Pass	08/09/2019				
5	16A to Double Socket	1	Visual 6mths & inspection test 12mths	08/03/2019	0.04	200		Pass	08/09/2019				
6	16A plug to 13A Plug	1	Visual 6mths & inspection test 12mths	08/03/2019	0.04	200		Pass	08/09/2019				
7	16A/ (2) 16A Splitter	1	Visual 6mths & inspection test 12mths	08/03/2019	0.03	200		Pass	08/09/2019				
8	16A/ (2) 16A Splitter	1	Visual 6mths & inspection test 12mths	08/03/2019	0.03	200		Pass	08/09/2019				
9	Orange Extension Cable	1	Visual 6mths & inspection test 12mths	08/03/2019	0.06	200		Pass	08/09/2019				
10	16A/ (2) 16A Splitter	1	Visual 6mths & inspection test 12mths	08/03/2019	0.03	200		Pass	08/09/2019				
11	16A/ (2) 16A Splitter	1	Visual 6mths & inspection test 12mths	08/03/2019	0.04	200		Pass	08/09/2019				
12	Orange Extension Cable	1	Visual 6mths & inspection test 12mths	08/03/2019	0.05	200		Pass	08/09/2019				
13	16A/ (2) 16A Splitter	1	Visual 6mths & inspection test 12mths	08/03/2019	0.04	200		Pass	08/09/2019				
14	16A/ (2) 16A Splitter	1	Visual 6mths & inspection test 12mths	08/03/2019	0.04	200		Pass	08/09/2019				

